

Idaho National Laboratory

TABLE OF CONTENTS	Identifier: TOC-59	
	Revision: 44	
	Effective Date: 03/29/07	Page: 1 of 3

Subcontractors	Table of Contents		DAR Number: N/A
----------------	-------------------	--	-----------------

Manual: Subcontractor Requirements

TAB	DOC. ID	SECTION OR DOCUMENT TITLE	REV
	LST-27	Glossary	6
	PDD-1001	Subcontractor Requirements Program Description – <u>Moved to INL Subcontractor Requirements</u>	--
1.		Administration	
	PRD-1002	Safeguards and Security Requirements	2
	PRD-1003	General Requirements	4
	PRD-1004	Stop Work Authority	0
	PRD-1006	Safety Surveillance	0
	PRD-1007	Work Coordination and Hazard Control	6
2.		Safety, Health, and Fire Protection	
	PRD-2001	Personal Protective Equipment	3
	PRD-2002	Fall Protection	3
	PRD-2003	Ladders	1
	PRD-2004	Scaffolding	3
	PRD-2005	Walking and Working Surfaces	1
	PRD-2006	Aerial Lifts and Elevating Work Platforms	1
	PRD-2007	Hoisting and Rigging	3
	PRD-2008	Steel Erection	2
	PRD-2009	Compressed Gases	0
	PRD-2010	Welding, Cutting, and Other Hot Work	1
	PRD-2011	Electrical Safety	1
	PRD-2012	Lockout and Tagout	4

Idaho National Laboratory

TABLE OF CONTENTS	Identifier: TOC-59
	Revision: 44
	Effective Date: 03/29/07 Page: 2 of 3

TAB	DOC. ID	SECTION OR DOCUMENT TITLE	REV
	PRD-2013	Concrete and Masonry	0
	PRD-2014	Excavations and Surface Penetrations	8
	PRD-2015	Hand and Portable Power Tools	5
	PRD-2016	Material Handling, Storage, and Disposal	3
	PRD-2019	Motor Vehicle Safety	1
	PRD-2020	Heavy Industrial Vehicles	4
	PRD-2022	Safety Signs, Color Codes, and Barriers	1
	PRD-2023	Temporary Facilities	2
	PRD-2024	Demolition	3
	PRD-2025	Explosives Safety	0
	PRD-2101	Hazard Communication	1
	PRD-2102	Disease Control	2
	PRD-2105	Lead	2
	PRD-2107	Heat and Cold Stress	4
	PRD-2108	Hearing Conservation	1
	PRD-2109	Respiratory Protection	3
	PRD-2110	Confined Spaces	2
	PRD-2111	Exposure Assessments	0
	PRD-2112	Lasers	0
	PRD-2201	Flammable and Combustible Liquid Storage	3
	PRD-2202	Fire Protection	0
3.		Radiological Control	
	PRD-3001	Radiological Control	3
4.		Environmental	
	PRD-4001	Environmental Requirements for Subcontractor Equipment and Services	2
5.		Quality Assurance	
	PRD-5001	Training and Indoctrination	3

Idaho National Laboratory

TABLE OF CONTENTS	Identifier: TOC-59 Revision: 44 Effective Date: 03/29/07	Page: 3 of 3
--------------------------	--	--------------

TAB	DOC. ID	SECTION OR DOCUMENT TITLE	REV
	PRD-5002	Design Change Control	5
	PRD-5003	Vendor Data Control	3
	PRD-5004	Procurement Document Control	2
	PRD-5005	Procedure Development	1
	PRD-5006	Subcontractor/Supplier Quality Plan (SQP)	1
	PRD-5007	Document Control	2
	PRD-5008	Control of Purchased Items	2
	PRD-5009	Material Traceability	1
	PRD-5010	Weld Record Packages and Piping Testing Packages	3
	PRD-5012	Survey Equipment Calibration and Control	1
	PRD-5014	Test Control	1
	PRD-5015	Control of Measuring and Test Equipment	2
	PRD-5016	Material and Equipment Storage, Handling, and Maintenance	2
	PRD-5017	Inspection and Test Status	1
	PRD-5018	Control of Nonconformance	1